



Wisconsin Electric POWER COMPANY
231 WEST MICHIGAN, MILWAUKEE, WISCONSIN 53201

DSB

November 16, 1979

Mr. James G. Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET 50-266
POINT BEACH NUCLEAR PLANT, UNIT 1
LICENSEE EVENT REPORT 79-018/01T-0

Enclosed is Licensee Event Report 79-018/01T-0 (a 14-day report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.9, "Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than that assumed in the accident analyses in the safety analysis report or Technical Specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or Technical Specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition."

Very truly yours,

Executive Vice President

Sol Burstein

Enclosures

NOV 19 1979
1437 532
S 7911300
559
A002
5/1