

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

November 23, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOIAH NUCLEAR PLANT UNITS 1 AND 2 - DAMAGED TUBES IN CONTAINMENT  
SPRAY HEAT EXCHANGER - NCR 16P - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
W. Cottle on October 25, 1979, in accordance with 10 CFR 50.55(e).  
Enclosed is our first interim report. We expect to submit our next  
report by February 1, 1980.

If you have any questions concerning this matter, please get in touch  
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure)✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

POOR ORIGINAL

1502 267

B017  
SE  
1/1