

1,
TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

21
November 15, 1979

Mr. James P. O'Reilly, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

PHIPPS BEND NUCLEAR PLANT, ALL UNITS - REPORTABLE DEFICIENCY - DEFECTIVE
REBAR FROM FLORIDA STEEL (NCR PBN-044)

Initial report of the subject deficiency was made to R. W. Wright,
NRC-OIE, Region II, on October 17, 1979. In compliance with paragraph
50.55(e) of 10 CFR Part 50, we are enclosing the final report of the
subject deficiency. If you have any questions regarding this matter,
please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

1552 330

8019
~~Am~~
SE
111