



Public Service Company
16805 Weld County Road 19 1/2,

CENTRAL FILES
PDR:HQ
LPDR
TIC
NSIC

November 1, 1979
Fort St. Vrain
Unit No. 1
P-79254

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

Docket No. 50-267

SUBJECT: Response to IE
Bulletin 79-24

Dear Mr. Seyfrit:

As requested in IE Bulletin 79-24, a field check of safety-related process, instrument, and sampling lines was initiated. The check of those lines which could possibly freeze during extremely cold weather revealed that all such lines were either inside heated buildings, heat traced, or heat traced and insulated. These measures should provide adequate protection against freezing.

If you have any questions, please contact me.

Very truly yours,

Don Warembourg
Don Warembourg
Manager, Nuclear Production

DW/alk

1758 297

8001160

582