

TIC

POWER AUTHORITY OF THE STATE OF NEW YORK

JAMES A. FITZPATRICK NUCLEAR POWER PLANT



JOHN D. LEONARD, JR.
Resident Manager

P.O. BOX 41
Lycoming, New York 13093

315-342-3840

May 9, 1979
JAFP-79-231

Mr. Boyce H. Grier, Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUBJECT: NRC I & E BULLETIN 79-04
INCORRECT WEIGHTS FOR SWING CHECK VALVES
MANUFACTURED BY VELAN ENGINEERING CORPORATION

REFERENCE: Letter from John D. Leonard, Jr. to Boyce H. Grier
Dated April 16, 1979 (JAFP-79-181)

Dear Mr. Grier:

The staffs of the Power Authority's FitzPatrick Plant, Headquarters Office and our Architect Engineer have reviewed the subject Bulletin. This review has shown that there are no high pressure (1500 psi) swing check valves manufactured by Velan Engineering Corporation installed in any seismic Category I piping systems or portions thereof at the FitzPatrick Plant.

In view of these findings, no re-analysis of piping with respect to Bulletin 79-04 is required.

If you should have any further questions in this matter, please contact us.

Very truly yours,


JOHN D. LEONARD, JR.

JDL:VC:brp

CC: G. T. Berry, PASNY, NYO
G. A. Wilverding, PASNY, NYO
P. W. Lyon, PASNY, NYO
M. C. Cosgrove, JAF
R. J. Pasternak, JAF
J. Helland, PASNY, NYO
Document Control Center

354

252

7907120066