



Public Service Company of Colorado

P. O. Box 361, Platteville, Colorado 80651

July 10, 1979
Fort St. Vrain
Unit No. 1
P-79148

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

REF: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/79-17/01-T-0, Final, submitted per the requirements of Technical Specification AC 7.5.2(a)5.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/79-17/01-T-0.

Very truly yours,

Don Warembourg
Manager, Nuclear Production

DW/alk

cc: Director, MIPC

*D002
S 1/1*

7907130 388

444 274