



Commonwealth Edison  
One First National Plaza, Chicago Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

TERA

7-124

May 29, 1979

Mr. James G. Keppler, Director  
Directorate of Inspection and  
Enforcement - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Subject: Byron Station Units 1 and 2  
Braidwood Station Units 1 and 2  
Response to I.E. Bulletin 79-04  
"Incorrect Weights for Swing  
Check Valves Manufactured by Velan  
Engineering Corporation"  
NRC Docket Nos. 50-454/455 and  
50-456/457

Reference (a): J. G. Keppler letter to B. Lee, Jr.  
dated March 30, 1979

Dear Mr. Keppler:

Reference (a) transmitted I.E. Bulletin 79-04 which required a response by all holders of operating licenses or construction permits for power reactor facilities.

We have reviewed the piping systems at Byron and Braidwood Stations and determined that a small number of 3, 4, or 6 inch swing check valves manufactured by Velan Engineering Corporation were furnished by the NSSS vendor -- Westinghouse. Correct weights have not been received from Velan as yet but are expected within 30 days. Correct weights will be used in the piping analyses and action will be taken to provide additional supports if indicated by the analyses.

No Velan swing check valves were purchased for the balance of plant piping systems.

350 307

Y 31 1979

7907160155

Mr. James G. Keppler:

- 2 -

May 29, 1979

Please direct any questions you may have concerning  
this matter to this office.

Very truly yours,

*Robert F. Jamieson*  
for Cordell Reed  
Assistant Vice-President

cc: Director, Division of Reactor  
Construction Inspection