

CONTROL BLOCK: 

						1
--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	3	4	7	0	6	0	8	7	9	3	0	7	0	8	7	9	9
60	61									68	69						74	75						80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

02 During the replacement of a shorted power cable on the 1B LHSI Pump Header Isolation

03 Valve which resulted in the valve being only locally operable, it was discovered the

04 cable was not installed according to its original cable pull ticket. The color-coded

05 cable had been incorrectly routed through two non-color-coded cable trays. Further

06 Investigation revealed one other cable to the 1B LHSI Pump Suction Valve from the

07 containment sump was also incorrectly routed through the same two cable trays.

08		9		80	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE	
S F 11		A 12		E 13	
COMP. SUBCODE		VALVE SUBCODE		COMPONENT CODE	
Z 15		Z 16		E L E C T R O N 14	
LER/RQ REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.	
17		7 9 21		0 1 6 24	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT	
C 18		Z 19		Z 20	
SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	
Z 21		0 0 0 22		N 23	
NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
N 24		Z 25		Z 9 9 9 26	

1 0 The incident resulted from the failure of construction personnel to install and  
1 1 verify per procedure the cable routings. The two cables will be rerouted and  
1 2 verified correct. An investigation has been undertaken to determine how many other  
1 3 cables were installed and verified by the two involved individuals. A program will  
1 4 then be developed to reverify a sampling of the cables.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	5	G	28	0	0	C	29	A	31	Operational event
7	8	9	10	11	12	13	14	15	16	17
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE				
1	6	Z	33	Z	34	N/A				
7	8	9	10	11	12	13	14	15	16	
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION				
1	7	0	0	0	37	Z	38	N/A		
7	8	9	10	11	12	13	14	15	16	
PERSONNEL INJURIES		NUMBER		DESCRIPTION						
1	8	0	0	0	40	N/A				
7	8	9	10	11	12	13	14	15	16	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION						
1	9	Z	42	N/A						
7	8	9	10	11	12	13	14	15	16	
PUBLICITY		ISSUED		DESCRIPTION						
2	0	N	44	N/A						
7	8	9	10	11	12	13	14	15	16	

PHONE: 412-643-1258