



Public Service Company of Colorado

P. O. Box 361, Platteville, Colorado 80651

July 12, 1979
Fort St. Vrain
Unit No. 1
P-79150

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

REF: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Abnormal Occurrence Report No. 50-267/76-19A, Final, submitted per the requirements of Technical Specification Section 2.1, paragraph f.

Also, please find enclosed one copy of the Licensee Event Report for Abnormal Occurrence Report No. 50-267/76-19A.

Very truly yours,

Don Warembourg

Don Warembourg
Manager, Nuclear Production

DW/alk

cc: Director, MIPC

*2002
5/11*

7907180 442

347 030