

LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	1	2	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4		5		
7	8	9	LICENTISE CODE					14	15	LICENSE NUMBER								25	26	LICENSE TYPE					30	57	CAT	58

CON'T

REPORT SOURCE 01 L 6 0 5 0 0 0 3 2 1 7 0 6 1 8 7 9 8 0 7 0 6 7 9 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (13)

On 6-18-79, at 1040 CST, while installing a 2 inch conduit in the main control station of the cable spreading room manual CO2 flooding system, a worker inadvertently started the timing relay which initiated alarms and later the CO2 deluge. Access to the area and stairwells was controlled while personnel with breathing apparatus isolated the discharge valve and performed a precautionary search of the cable spreading room. The 13 ton storage tank level dropped from 90% to 40% violating Tech Spec 3/4.13.4 which requires 60% minimum level. There were no previous occurrences of this event.

SYSTEM CODE A B 11		CAUSE CODE A 12		CAUSE SUBCODE E 13		COMPONENT CODE R E L A Y X 14		COMP. SUBCODE M 15		VALVE SUBCODE Z 16	
EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 3 9 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN X 18 33		FUTURE ACTION 19 34		EFFECT ON PLANT Z 20 35		SHUTDOWN METHOD Z 21 36		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23 41	
NPRD-4 FORM SUB. N 24 42		PRIME COMP. SUPPLIER A 25 43		COMPONENT MANUFACTURER C 1 2 5 26 44 47							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The timer initiation relay was located about 2 inches away from the point at which
11 the worker was installing the conduit to add automatically closing fire dampers to the
12 system. Continuous fire watches were established at unprotected areas and hose reel
13 locations until the following day when the tank was refilled and the system was ret-
14 urned to service.

7 8 9
FACILITY STATUS (1) 5 (28) 0 0 0 (29) N/A (30) METHOD OF DISCOVERY (31) A (32) Operator Observation (33) DISCOVERY DESCRIPTION (34) 7907180499 S

7 8 9 10 11 12 13 14 15 16
ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (2) Z (33) (3) Z (34) N/A (35) LOCATION OF RELEASE (36) N/A

7 8 9 10 11 12 13 14 15 16
PERSONNEL EXPOSURES NUMBER (1) 7 (2) 0 (3) 0 (4) 0 (5) 1 (6) Z (38) N/A

7 8 9 10 11 12 13 14 15 16
PERSONNEL INJURIES NUMBER (1) 1 (2) 0 (3) 0 (4) 0 (5) 1 (6) Z (40) N/A

7 8 9 10 11 12 13 14 15 16
LOSS OF OR DAMAGE TO FACILITY TYPE (1) 1 (2) Z (42) N/A

7 8 9 10 11 12 13 14 15 16
PUBLICITY ISSUED DESCRIPTION (1) 0 (2) N (44) N/A

7 8 9 10 11 12 13 14 15 16
NRC USE ONLY

NAME OF PREPARER T. V. Greene, Supt. Plt. Eng. Serv.

PHONE 912-367-7781