



## Public Service Company of Colorado

P. O. Box 361, Platteville, Colorado 80651

July 12, 1979  
Fort St. Vrain  
Unit No. 1  
P-79151

Mr. Karl V. Seyfrit, Director  
Nuclear Regulatory Commission  
Region IV  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76012

REF: Facility Operating License  
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/77-17(14)A, Final, submitted per the requirements of Technical Specification AC 7.5.2(a)5.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/77-17(14)A.

Very truly yours,

*Don Warembourg/m*

Don Warembourg  
Manager, Nuclear Production

DW/alk

cc: Director, MIPC

7  
7907180568346 109  
D002  
5/11