

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1

PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION

01 A R A N 0 1 02 0 0 - 0 0 0 0 0 - 0 03 4 1 1 1 1 04 1 05 1

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 36

01 L 02 6 03 0 04 5 05 0 06 0 07 3 08 1 09 3 10 7 11 0 12 6 13 1 14 6 15 7 16 9 17 0 18 7 19 1 20 6 21 7 22 9

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During unit heatup, Emergency Feedwater pump, P7B, was

03 automatically started with an inadvertant SLBIC actuation.

04 SLBIC actuated due to a valve lineup error. The EFW

05 pump was stopped after 26 minutes. At that time it was

06 identified that the outboard pump bearing was extremely

07 hot. Both EFW pumps are required to be operable during heatup and

08 operation per T.S.3.4.1.4. Similar to LER 50-313/77-003. Reportable per

09 T.S.6.12.3.2b.

09 C H 11 E 12 B 13 P U

SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 12 13 COMPONENT CODE 14 15 COMP. SUBCODE 15 16 VALVE SUBCODE 20

17 7 9 18 0 0 7 19 0 3 20 L 21 0 22 0

LER/RO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32

01 A 02 G 03 Z 04 Z 05 0 06 0 07 0 08 0 09 N 10 Y 11 A 12 0 13 7 14 5

ACTION TAKEN 33 34 FUTURE ACTION 35 36 EFFECT ON PLANT 37 38 SHUTDOWN METHOD 39 40 HOURS 41 42 ATTACHMENT SUBMITTED 43 44 NRC-4 FORM SUB 45 46 PRIME COMP SUPPLIER 47 48 COMPONENT MANUFACTURER 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Investigation revealed that the bearing had failed due to

11 faulty installation during previous preventive maintenance.

12 The maintenance procedure has been revised to

13 provide clear-cut instructions. Pump bearing was replaced

14 and pump returned to service.

15 C 16 0 17 0 18 0 19 NA 20 A 21 NA 22 NA

FACILITY STATUS 28 29 % POWER 30 31 OTHER STATUS 32 33 METHOD OF DISCOVERY 34 35 DISCOVERY DESCRIPTION 36 37

16 Z 17 Z 18 NA 19 NA 20 NA 21 NA 22 NA

ACTIVITY CONTENT 38 39 RELEASED OF RELEASE 40 41 AMOUNT OF ACTIVITY 42 43 LOCATION OF RELEASE 44 45

17 0 0 0 18 Z 19 NA 20 NA 21 NA 22 NA

PERSONNEL EXPOSURES 37 38 TYPE 39 40 DESCRIPTION 41 42

18 0 0 0 19 NA 20 NA 21 NA 22 NA

PERSONNEL INJURIES 40 41 DESCRIPTION 42 43

19 Z 20 NA 21 NA 22 NA

LOSS OF OR DAMAGE TO FACILITY 42 43 DESCRIPTION 44 45

20 NA 21 NA 22 NA

PUBLICITY 44 45

20 NA 21 NA 22 NA

ISSUED DESCRIPTION 45 46

20 NA 21 NA 22 NA

NRC USE ONLY

NAME OF PREPARER Chris N. ShivelyPHONE 501-968-2519

79072 30354

413 089