



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

June 11, 1976

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm our verbal report to NRC RO: III Inspector, Mr. K.R. Baker, on June 11, 1976. In that conversation we reported that Radiation Monitor R-19 was out of service while blowing down the steam generator during moisture carryover testing. Grab samples were taken but the blowdown demineralizers were not placed in service in violation of Appendix B Technical Specifications Section 2.4.2.g.

A complete report will be submitted within 7 days as required by Appendix B Technical Specification Section 5.4.2.1.

Sincerely,

for R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R. Kilburn
R.J. Vollen BPI
R.C. Callen MPSC
K.R. Baker RO:III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
R.S. Keith
PNSRC
Dir., IE (20 copies)
Dir., MIPC (2 copies)
Dir., Licensing (1 copy)

