

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE ARAN02 LICENSE NUMBER 00000000000000000000 LICENSE TYPE 41111 CAT 5

CON'T

REPORT SOURCE L DOCKET NUMBER 050003687061979 EVENT DATE 071879

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While performing surveillance test OP2304.15 on the inner seal on contain-
ment penetration 2C2, Personnel escape hatch, it was noted that the leakage
of the seal was in excess of 50,000 cc/minute. The outer seal was tested
and found to have no leakage; therefore, the public health and safety
was not affected. There have been no similar occurrences. Reportable per
T.S.6.9.1.9b

SYSTEM CODE SD CAUSE CODE E CAUSE SUBCODE R COMPONENT CODE PENETR COMP. SUBCODE A VALVE SUBCODE Z

LER-RO REPORT NUMBER 79 SEQUENTIAL REPORT NO. 046 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0

ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

A Z Z Z 0000 N N A W300

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The inner Personnel escape hatch seal was visually inspected with no
degradation noted. The seal was replaced and retes indicated no leakage.
The containment air lock was returned to service within 3 hours of failure
detection, meeting the requirements of Action Statement T.S.3.6.1.3b.

FACILITY STATUS B % POWER 0000 OTHER STATUS Mode 3 METHOD OF DISCOVERY B DISCOVERY DESCRIPTION Surveillance Test

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

PERSONNEL EXPOSURES NUMBER 000 TYPE Z DESCRIPTION NA

PERSONNEL INJURIES NUMBER 000 DESCRIPTION NA

LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION NA

PUBLICITY ISSUED DESCRIPTION NA

NAME OF PREPARER Chris N. Shively PHONE 501/968-2519

414

327

234

7907300 307

S