

79-028-03L
79-025-03L

1E MAIL

USNRC
JUL 6 8:52

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

July 3, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - ERCW VALVE POSITIONING -
NCR MEB 79-22 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector Bob Wright on June 7, 1979, in accordance with 10 CFR 50.55(e). Enclosed is our final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

L. M. Mills

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

437 287

B019
S 1/1 2

7908020482

790369

OFFICIAL COPY