



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

June 28, 1979

2-069-15

Mr. K.V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX. 76011

Subject: Arkansas Nuclear One-Unit 2  
Docket No. 50-368  
License No. DPF-6  
Reportable Occurrence Report  
Nos. 50-368/79-40 & 50-368/79-43  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.8, we have attached the subject reports concerning the inoperability of the Emergency Feedwater flow control valve to stroke shut or respond to a MSIS signal (50-368/79-40) and the inoperability of an Emergency Feedwater valve to close upon a control room demand signal (50-368/79-43).

Very truly yours,

*John M. Gifford*  
David C. Trimble  
Manager, Licensing

ECT:gp

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX. 76011

Mr. W.D. Johnson  
U. S. Nuclear Regulatory Comm.  
P. O. Box 2090  
Russellville, AR. 72801

Mr. Norman M. Haller, Director  
Office of Management and  
Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

309 063