

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EYES - DESCRIPTION AND MEASUREMENTS CONTINUED (10)[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

2 0 N N/A
P. T. Nix, Supt. of Maine. 163 314

7907230473

NAC USE ONLY

P. T. Nix, Supt. of Mair.

A63 314

Georgia Power Company
Plant E. I. Hatch
Saxley, Georgia 31513

Cause Description and Corrective Actions (continued)

correct alignment of the valve and the mounting flange centerline, each time the valve is reassembled.

Main steam safety relief valve discharge line vacuum breaker valves (2B21 F037-C,D,E,F,G,H,I,J.) were also inspected and found to be in good repair with no apparent problems.

An update will be submitted when the final resolution has been made.