

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER												25	LICENSE TYPE						30	57 CAT 58		

CON'T

0 1 7 8

REPORT SOURCE

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 2315 the Unit 2 containment gaseous and particulate radioactivity monitoring
0 3 | systems failed due to a loss of the sampling pump (T.S.3.4.6.1.). The pump was
0 4 | restarted at 0001 6/20/79, returning the gaseous and particulate radioactivity
0 5 | monitoring systems to service. The containment sump level alarm system remained
0 6 | operable during the event.

SYSTEM CODE B B		CAUSE CODE X	CAUSE SUBCODE X	COMPONENT CODE Z Z Z Z Z Z				COMP. SUBCODE Z	VALVE SUBCODE Z
0	9								
7	8	9	10	11	12	13	14	15	16
LER/RO REPORT NUMBER 7 9		EVENT YEAR 7 9	SEQUENTIAL REPORT NO. 0 2 2	OCCURRENCE CODE 0 3	REPORT TYPE L	REVISION NO. 0			
21	22	23	24	25	26	27	28	29	30
ACTION TAKEN Z	FUTURE ACTION Z	EFFECT ON PLANT Z	SHUTDOWN METHOD Z	HOURS 0 0 0 0		ATTACHMENT SUBMITTED N	NPRD-4 FORM SUB. N	PRIME COMP. SUPPLIER Z	COMPONENT MANUFACTURER Z 9 9 9
33	34	35	36	37	38	39	40	41	42
17	18	19	20	21	22	23	24	25	26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

As stated above, pump was restarted approximately 45 minutes after it stopped; no specific maintenance action had been taken to determine or correct the cause of the failure. It is supposed that a spurious high flow signal occurred causing the running pump to trip and preventing the backup pump from starting. Since the exact initiating event could not be duplicated, no further maintenance action could be taken.

7 8 9
FACILITY STATUS (28) 1 5 E
10 11 12 13
% POWER 1 0 0 (29) NA OTHER STATUS (30)
44
45 46 47 48 49
METHOD OF DISCOVERY A (31) Operator Observation DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
1 7	Z Z Z (37)	(38) NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	0	0	0
2	0	0	0
3	0	0	0
4	0	0	0
5	0	0	0
6	0	0	0
7	0	0	0
8	0	0	0
9	0	0	0
10	0	0	0
11	0	0	0
12	0	0	0
13	0	0	0
14	0	0	0
15	0	0	0
16	0	0	0
17	0	0	0
18	0	0	0
19	0	0	0
20	0	0	0
21	0	0	0
22	0	0	0
23	0	0	0
24	0	0	0
25	0	0	0
26	0	0	0
27	0	0	0
28	0	0	0
29	0	0	0
30	0	0	0
31	0	0	0
32	0	0	0
33	0	0	0
34	0	0	0
35	0	0	0
36	0	0	0
37	0	0	0
38	0	0	0
39	0	0	0
40	0	0	0
41	0	0	0
42	0	0	0
43	0	0	0
44	0	0	0
45	0	0	0
46	0	0	0
47	0	0	0
48	0	0	0
49	0	0	0
50	0	0	0
51	0	0	0
52	0	0	0
53	0	0	0
54	0	0	0
55	0	0	0
56	0	0	0
57	0	0	0
58	0	0	0
59	0	0	0
60	0	0	0
61	0	0	0
62	0	0	0
63	0	0	0
64	0	0	0
65	0	0	0
66	0	0	0
67	0	0	0
68	0	0	0
69	0	0	0
70	0	0	0
71	0	0	0
72	0	0	0
73	0	0	0
74	0	0	0
75	0	0	0
76	0	0	0
77	0	0	0
78	0	0	0
79	0	0	0
80	0	0	0
81	0	0	0
82	0	0	0
83	0	0	0
84	0	0	0
85	0	0	0
86	0	0	0
87	0	0	0
88	0	0	0
89	0	0	0
90	0	0	0
91	0	0	0
92	0	0	0
93	0	0	0
94	0	0	0
95	0	0	0
96	0	0	0
97	0	0	0
98	0	0	0
99	0	0	0
100	0	0	0

8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE DESCRIPTION

1 9 Z (42) NA 7907250304

8 9 10 80

PUBLICITY

ISSUED DESCRIPTION (45) NR USE ONLY

2 0 N (44) NA 510 094

NAME OF PREPARER S. M. Davis/J. S. Lagiewski

PHONE: (301) 234-7942