



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 25, 1979

1-079-10

Mr. K. V. Seyfrit, Director  
Office of Inspection  
and Enforcement  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 1  
Docket No. 50-313  
License No. DPR-51  
Reportable Occurrence Report  
No. 50-313/79-008  
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 1 Technical Specification 6.12.3.2, we have attached the subject report concerning an Emergency Feed Actuation being received when the "A" OTSG startup level transmitter selection was shifted.

This report is being submitted late due to inadvertent delay in processing. We hope this does not cause you much inconvenience.

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

OCT:nak

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

543 277

7907310444 S

Mr. Norman Haller, Director  
Office of Management and  
Program Analysis  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. W. D. Johnson  
U.S. Nuclear Regulatory Commission  
Post Office Box 2090  
Russellville, Arkansas 72801

543 278