



VIRGINIA ELECTRIC AND POWER COMPANY, RICHMOND, VIRGINIA 23261

July 27, 1979

Mr. James P. O'Reilly, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. 539A
PSE&C/GLP:adw:mc
Docket No. 50-339

Dear Mr. O'Reilly:

In our 5 day report Serial No. 539 concerning Steam Generator level errors during accident conditions we indicated that the problem was being studied by Westinghouse.

We have been informed by Westinghouse that further evaluation of the problem is required therefore we are sending this letter as an interim report on this matter.

Work is continuing and we are trying to formulate a viable solution to this problem. We will continue to work with Westinghouse and to keep you informed of the progress on this problem.

Very truly yours,

Sam C. Brown, Jr.
Senior Vice President-Power Station
Engineering and Construction

cc: Mr. Victor Stello, Director
Office of Inspection & Enforcement

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation

Boia
S
1/0

(1)

480

200

7908010396