

1E MAIL

7903903L
7903203L

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

July 5, 1979

JUL 6 4:51

Mr. James P. O'Reilly
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - SEAL WATER INJECTION FLOW
ELEMENTS HAVE WRONG ORIFICE SIZE - NCR MEB 79-21 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
D. G. Hinckley on June 7, 1979, in accordance with 10 CFR 50.55(e).
Enclosed is our final report.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

13019
S 1/1

486 262
1908020453

790367