

327179031
328171026

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

70 JUL 16 8 2: 36
July 16, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - CONDUIT JUNCTION BOXES INSIDE
CONTAINMENT - NCR EEB 79-7 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
W. T. Cottle on June 15, 1979, in accordance with 10 CFR 50.55(e).
Enclosed is our final report. This deficiency was also identified at
Watts Bar Nuclear Plant as NCR EEB 79-8.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager

Nuclear Regulation and Safety

Enclosure

cc: Director of Inspection and Enforcement (Enclosure)
U.S. Nuclear Regulatory Commission
Washington, DC 20555

13019
S 1/1

508 252

79080300865

790385

OFFICIAL COPY