

the

SEABROOK STATION
Engineering Office:
20 Turnpike Road
Westborough, MA 01581

July 12, 1979

SB-8012
T.F. B 4.2.5

United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attention: Office of Inspection and Enforcement

Reference: 1. Docket No. 50-443 and 50-444
2. NRC letter dated May 22, 1979
3. IE Bulletin 79-11

Subject: Faulty Overcurrent Trip Device in Circuit Breakers for
Engineered Safety Systems

Dear Sir:

We have reviewed the referenced IE Bulletin 79-11 and have determined that we are not using this device in any safety related service in the Seabrook design.

Very truly yours,

David A. Mairland
John DeVincentis *for*
Project Manager

DAM:tla

cc: B.B. Beckley
J.H. Herrin
W.E. Wright

522 264

7908070 705 0