

79046032
79037032

Headquarters

TELEPHONE REPORT

ALL: 05

FACILITY: Sequoyah Unit #1+2 DOCKET #: 050-327/328
DATE: 7/30/79 TIME: 1600 LIC. OCC. #: CPPR-72
SUBJECT: Possible Reportable Item per 50.55(c)

DESCRIPTION OF OCCURRENCE: Electrical handholes in
conduit between auxiliary Building
and AERCW Pump Station has not been
seismically qualified or checked for
flotation and stresses during the probable
maximum flood.

TVA item # NCR-COB-79-04
TVA is evaluating reportability under
10CFR 50.55(c). Decision due by 8/9/79.

Thomas J. Donat

POOR ORIGINAL

FORM RII-T-12

3019
5 0/1

647 031

7908140576