

790-44-03L

790-36-03L

*Handwritten*USNRC ETC  
TELEPHONE REPORT

10 JUL 30 A 9:21

FACILITY: Sequoyah 1 and 2

DOCKET #: 50-327  
50-328

DATE: 7/27/79

TIME: 4:00 p.m.

LIC. OCC. #: SWP-79-S-9

SUBJECT: Potential CDR: Inadequate Design of 3/4" Test Lines on Safety

Injection Header

DESCRIPTION OF OCCURRENCE: Licensee reported that the 3/4" test lines from the 8" low head safety injection headers as designed do not allow for acceptable piping flexibility per ANSI B31.7 during particular transients. The licensee is evaluating this problem for applicability to Watts Bar Units 1 and 2. If determined reportable a 30-day report is due 8/27/79

**POOR ORIGINAL**

M. J. Gouge

SIGNATURE

Bo19  
50/1628 147  
7908140 718 S  
790404