

TIC

Southern California Edison Company

P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

K. P. BASKIN
MANAGER, GENERATION ENGINEERING

May 24, 1979

TELEPHONE
213-572-1401

U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 N. California Boulevard
Walnut Creek, California, 94596



Attention: Mr. R. H. Engelken, Director

Gentlemen:

Subject: IE Bulletin 79-04
Docket No's. 50-361 and 50-362
San Onofre Nuclear Generating Station
Units 2 and 3

Your letter of March 30, 1979, transmits IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Manufactured by Velan Engineering Corporation", and describes instances of potentially incorrect piping stress analyses for those systems utilizing Velan swing check valves due to a discrepancy between the valve weights described on design drawings and the actual weights supplied.

Please be advised that a review of all project documentation was performed and it has been determined that Velan has not supplied, nor are they scheduled to supply, the subject valves for use at San Onofre Units 2 and 3. As such, the specific actions identified in the bulletin are not applicable to this project.

Should you have any questions or require further clarification, please contact me.

Very truly yours,

KP Baskin

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspections
Washington, D. C. 20555

304 324

7907090235

79-88