

USNRC REGION II
ATLANTA, GEORGIA

79 JUN 4 A9:31



May 29, 1979
L-79-150

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 M. Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: NRC OPO
50-250, 50-251
IE Bulletin 78-12B

A status report is attached describing our progress in responding to the subject Bulletin as it applies to Turkey Point Units 3 and 4.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/ms

Attachment

cc: Robert Lowenstein, Esquire

344 226

7907130305

790279
OFFICIAL COPY

ATTACHMENT

Re: RII:JPO
50-250, 50-251
IE Bulletin 78-12B

Florida Power & Light Company (FPL) was recently informed by Westinghouse Electric Corporation that they have evaluated the information contained in the Babcock & Wilcox generic report that was transmitted to the NRC by letter dated March 13, 1979. Westinghouse has concluded that the weld material data and other required information pertinent to the Turkey Point Unit 3 reactor vessel are included in the generic report. (Turkey Point Unit 4 was one of the twelve units identified in IE Bulletins 78-12 and 12A as possibly having atypical weld material.)

We are in the process of reviewing the information received from Westinghouse (by letter dated May 23, 1979) and plan to complete the FPL response to item 2 of Bulletin 78-12B by June 29, 1979.

344 227