


CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER								25	26	LICENSE TYPE					30	57	CAT	58

CON'T

REPORT SOURCE: 0 1 7 8
DOCKET NUMBER: L 6 0 5 0 - 0 2 2 5 7 1 2 0 2 7 8 8 0 7 0 9 7 9 9
EVENT DATE: 60 61 68 69 74 75 80
REPORT DATE: 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While inserting control rods to decrease reactor power, the operator observed that

03 position indication for notch 18 and 28 was inoperable for rod 02-23.

04 | (Technical Specification 3.1.3.7,6.9.1.9b)

05 _____

08 _____

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE			
0	9	I	D	E	A	I	N	S	T	R	U	E	Z				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17	7	8		0	9	3		0	3	X	1						
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
B	Z	Z	Z	0	0	0	N	N	N	N	G	0	8	0			
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 During the outage, the PIP probe was checked and a ground was found on switch 48. The

switch was covered with fiberglass tape and the position indication for rod 02-23 was

1 2 returned to normal. This is considered an isolated incident and no further action is

1	2
---	---

 required.

1	4
---	---

FACILITY STATUS				% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	(28)	0	5	1	(29)	NA	A	(31)	Operator Surveillance	
7	8	9		10	11	12	13		44	45	46	

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA

7 8 9 10 11 44

NA LOCATION OF RELEASE (36)

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA (39)				

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

		LOSS OF OR DAMAGE TO FACILITY				
		TYPE	DESCRIPTION	(43)		
1	9	Z	(42) NA		361	107

PUBLICITY		ISSUED		DESCRIPTION		7907130 363		NRC USE ONLY	
2	0	N	44	NA					

NAME OF PREPARER

A. C. Tollison, Jr.

PHONE 9

919-457-9521

NRC USE ONLY