

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

July 11, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DFR-33 - REPORTABLE OCCURRENCE
REPORT BFRD-50-259/798

The enclosed report provides details concerning pressure switches
PS-1-81 A and B and PS-1-91 A and B setpoints which exceeded Technical
Specification Table 3.1.A limits by 3 to 15 psig during normal
operation while performing Surveillance Instruction 4.1.A-14, turbine
first stage pressure permissive. This report is submitted in accordance
with Browns Ferry unit 1 Technical Specification 6.7.2.b.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

576 017

576061

Acc 2
5/11

POOR ORIGINAL