

BOSTON EDISON COMPANY

TELECOPY MESSAGE

To: _____
Telephone Number _____

Date/Time: 7-5-79 / 1500

To: Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406From: Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, MA 02360Subject: PROMPT REPORTABLE OCCURRENCE
Docket Number 50-293; License DPR-35

Assigned LER Number 79-019/01X-U

Event Description: On July 5, 1979, PNP3 was informed that Bechtel had discovered an error in their calculations in support of Amendment 34 to the FSAR which could have the effect of higher analyzed compartment peak pressures for assumed pipe breaks.

Cause and Corrective Action: The cause of the error was the assumption that the reactor building truck lock doors were open to the atmosphere rather than closed. Bechtel is reanalyzing using a corrected computer model.

Facility Status:

- a) Routine Startup _____
d) Routine Shutdown _____
e) Steady State x _____
f) Load Changing _____

100 % Thermal MW

- g) Shutdown _____
h) Refueling _____
i) Other _____
j) Not Applicable _____

A written follow-up report will be sent within two weeks.

NRC person notified Mr. R. Archibald

Prepared by Mr. E.J. Mathis

Mail (2) copies to:

Director
Office of Manpower Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

POOR ORIGINAL

7907190308

324 004