


LICENSEE EVENT REPORT

CONTROL BLOCK: 

(USE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | G | A | E | I | H | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

C T
0 1
7 8

REPORT SOURCE L 6 0 5 0 0 0 3 2 1 7 0 7 1 0 7 9 8 0 7 1 8 7 9 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing weekly surveillance test HNP-1-3052 on IRM'S the instrument

0 3 | technician failed to check the down scale alarm and the rod out block alarms. There

0 4 | was no fuel in the vessel, a rod block was present and the reactor trip circuit

0 5 | already scrambled. There was no effect on public health or safety.

0 6 |

0 7 |

0 8 |

7 8 9 80

SYSTEM CODE I A 11		CAUSE CODE A 12		CAUSE SUBCODE C 13		COMPONENT CODE Z Z Z Z Z Z 14		COMP SUBCODE E 15		VALVE SUBCODE Z 16							
EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 4 6 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN G 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 40		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER Z 25		COMPONENT MANUFACTURER Z 9 9 9 26 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The procedure only covered "run" and "shutdown" modes of operation. The mode

1 1 switch was in "refuel" and the technician was confused since the alarms were

1 2 already present. The procedure was revised and the technician cautioned not to

omit steps in the procedure.

7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60													
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
FACILITY STATUS		H		28		29		N/A		30		METHOD OF DISCOVERY		31		NRC Inspection		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60																																													

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

AMOUNT OF ACTIVITY (35)
N/A

LOCATION OF RELEASE (36)
N/A

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	(37)	Z	(38)	N/A		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	4	0	0	0	N/A

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
[Z] (42)	N/A	7907260 847 S

PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY																	
2	0	N	44	N/A																			
7	8	9	10																				

NAME OF PREPARER R. T. Nix

424

PHONE 1-800-291-367-7781