



TERA  
TERA  
Stephen H. Howell  
Senior Vice President

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 • (517) 788-0453

June 15, 1979  
Howe 171-79

Mr J G Keppler, Regional Director  
Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

MIDLAND PROJECT  
DOCKET NO 50-329, 50-330  
IE BULLETIN 79-09  
FILE: 0505.12 SERIAL: 7152

We have reviewed IE Bulletin 79-09 on "Failures of GE Type AK-2 Circuit Breakers in Safety Related Systems" against the Midland Plant design and the following response is provided.

In the Midland Plant safety related systems, General Electric Type AK-2 circuit breakers are used only in the Control Rod Drive Control System. A procedure has been identified and entered into the Master Procedure Index to cover Preventive Maintenance on these breakers using the guidelines of General Electric Service Advice Letter 175 (CPDD) 9.3.

It is expected that the procedure will be completed and approved by September 1979. Preventive Maintenance utilizing this procedure will initially be performed by qualified personnel at a six month interval and will commence after acceptance testing which is scheduled for April 1980 for Unit 2.

SHH/jm

CC: Director, NRC Office of Inspection & Enforcement  
Director, Nuclear Reactor Regulation

569323

JN 20 1979

7907300531