

**Detroit  
Edison**

Edward Hines  
Assistant Vice President  
Quality Assurance

3331 W. Big Beaver Road  
Troy, Michigan 48064  
313 649-1122

PDR

May 25, 1979  
EF2-46,146

Mr. James G. Keppler  
Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Subject: Detroit Edison Response to IE Bulletin No. 79-04

This letter is in response to your letter No. 50-341, IE Bulletin 79-04, dated March 30, 1979, which describes incorrect weights for swing check valves manufactured by Velan Engineering Corporation.

Enclosed please find our response to your inquiry in our memorandum EF2-45,204 of May 24, 1978.

Please advise us if you require further action by us regarding this matter.

Sincerely yours,

*Edward Hines*

RWB/lm

Encl.

cc: Mr. John G. Davis, Acting Director  
Office of Inspection and Enforcement  
Division of Reactor Inspection Programs  
U.S. Nuclear Regulatory Commission  
Washington D.C. 20555

446 225

5/1/1979

7908020 265

ENRICO FERMI UNIT 2 PROJECT  
ENGINEERING

RECEIVED

MAY 25 1979

May 24, 1979

R. W. BARR

EF2 - 45204

To: R. W. Barr  
Project QA Director - EF2  
206 Engineering Construction-Troy

From: R. E. Grego  
System Engineer - EF2  
318 Engineering Construction-Troy

Reference: 1E-Bulletin No. 79-04, dated March 30, 1979

Subject: Fermi 2 Response Regarding Velan Check Valves

We have reviewed the above referenced bulletin and our valve purchase orders, and have determined that NO Velan Swing Check Valves are used in Safety-related Systems of the Fermi 2 nuclear power plant. We, therefore, consider this item closed.

FEG/dk

cc: M. G. Sigetich  
W. F. Colbert  
G. J. Butterworth  
Document Control

446 226