

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

June 8, 1979

Mr. J. A. Hind, Chief  
Office of Inspection & Enforcement  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Hind:

Docket 50-305  
Operating License DPR-43  
IE Inspection Report 50-305/79-04

Enclosed please find the response to the referenced inspection report conducted by Messrs Creed and Madala of your office. The areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of Title 10, Code of Federal Regulations, and, therefore, our response contained in the enclosure to this letter should not be placed in the Public Document Room.

In Mr. A. Schwencer's letter of April 10, 1979, which transmitted approval of the Kewaunee Nuclear Power Plant Industrial Security Manual, the Division of Operating Reactors recognizes that full implementation of the Industrial Security Manual will require some time. This letter further states, "When all aspects of your approved plan have been implemented, we request that you notify both the Office of Inspection and Enforcement and the Office of Nuclear Reactor Regulation, at which time a compliance inspection will be scheduled by the Office of Inspection and Enforcement."

The subject inspection occurred less than two weeks after approval of the Kewaunee Industrial Security Manual and evidently was not intended to be the compliance inspection referenced above. We feel that four of the six items of noncompliance cited in the referenced inspection report were isolated incidents that would not have occurred once we had a chance to fully implement and audit the security systems and procedures provided for in the Security Plan and assured by Mr. Schwencer's letter. This week long

446 228

ATTACHMENT CONTAINS  
■ CFR 2.790 (d) INFORMATION


✓ 11 1979

7908020267

Mr. J. A. Hind  
June 8, 1979  
Page 2

security inspection came at a period of time when efforts to implement the newly approved security plan were in progress and detracted from those efforts because of the corporate and plant staff manpower required to support the inspection activity and answer the items cited as a result of the inspection.

Very truly yours,



E. R. Mathews, Vice President  
Power Supply and Engineering

snf

Attach.

446 229