

RO TELEGRAM FORMAT

01 BAXLEY, GEORGIA 31513
PMS MR. JAMES P. O'REILLY
UNITED STATES NUCLEAR REGULATORY COMMISSION
DIRECTOR OF INSPECTION AND ENFORCEMENT
REGION II
SUITE 3100
101 MARIETTA STREET
ATLANTA, GEORGIA 30303

USNRO REGION
ATLANTA, GEORGIA

79 JUL 23 A7:51

L. P. O'REILLY
C. M. UPRIGHT
P. D. CRENDEN
W. B. KENNA
F. J. LONG
C. E. MURPHY
J. T. SUTHERLAND
E. M. CLARK

SUBJECT: WACH UNIT 1, BUCKET NO. 50-321,
OCCURRENCE NO. 50-321/1979-48

DATE: 7/20/79

NOTIFICATION OF REPORTABLE
NOTIFIED: Ross F. Rogers

DATE: 7/20/79
TIME: 5:00 pm

DESCRIPTION OF REPORTABLE OCCURRENCE

Initial Condition

Shutdown for maintenance and Refueling

Nature of Occurrence:

While performing preventative maintenance on 600V BUS
(GE AR25) circuit breakers, it was found that the overcurrent trips
for Essential Motor Control Centers R24-5011 (DIVISION I) AND
R24-5012 (DIVISION II) WERE 300 AMP instead of 600 AMP.

Immediate Corrective Action:

Replace 300 AMP trip devices with 600 AMP trip devices
and return to service.

A002
51/0

423 360

7808020439