

TELEPHONE REPORT

~~SECRET~~  
HID

FACILITY: Sequoyah Unit 1 DOCKET #: 50-327

DATE: 7/17/79 TIME: 1100 LIC. OCC. #: \_\_\_\_\_

SUBJECT: SS Accumulator Discharge  
Valve Stellite Face Cracks

DESCRIPTION OF OCCURRENCE: Potential CDL 50.55(e)  
Inspection of two SS accumulator  
discharge valves revealed severe multiple  
cracks in the stellite facing on the  
valves. Valon Engineering, the valve  
manufacturer has been notified by  
the licensee. Possible generic impli-  
cations on Sequoyah Unit 2 and  
Watts Bar Units 1 and 2.

3019  
S O/I

**POOR ORIGINAL**

FORM 811-1-12

500

305

7/17/79

489

174

7908030402

790388

A. Bilisla