



UNIVERSITY OF MISSOURI

TERA TERA

Research Reactor Facility

Research Park
Columbia, Missouri 65211
Telephone (314) 882-4211

June 30, 1979

United States Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Docket No. 50-186
Re: Inspection Report No. 050-186/79-03

Gentlemen:

Please change the MURR Reactor Operations Annual
Report 1977-78 page 27 as follows:

Liquid Effluent--7/1/77 to 6/30/78

<u>Nuclide</u>	<u>Amount (Ci)</u>
H-3	0.130597

change entry to

H-3	0.1333
-----	--------

The change reflects a calculation of the minimum
detectable sample value times the total volume released to
the sanitary sewer via the secondary cooling system.

Sincerely,

Orval L. Olson

Orval L. Olson, Manager
Reactor Health Physics


Endorsement:
Reviewed and approved

Robert M. Brugger

Robert M. Brugger
Director, Research
Reactor Facility

501 329

OLO/mbs



COLUMBIA KANSAS CITY ROLLA ST. LOUIS

an equal opportunity institution

JUL 6 1979

7908080 402