

327/79049
328/79039

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower, #1

August 1, 1979

Headquarters

9/1/79 10:16

RECEIVED

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - MISSING SUPPORT FOR AUXILIARY
FEEDWATER PUMP TRIP AND THROTTLE VALVE - NCR MEB 79-35 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
T. J. Donat on July 6, 1979, in accordance with 10 CFR 50.55(e).
Enclosed is our final report. An identical nonconformance has been
reported on Watts Bar Nuclear Plant as NCR MEB 79-36.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

*B019
5/1*

678300

7908150 526

An Equal Opportunity Employer

790423
ORIGINAL COPY