



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

August 29, 1979

2-089-17

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 2
Docket No. 50-368
License No. NPF-6
Reportable Occurrence Report
Nos. 50-368/79-060; 50-368/
79-061; and 50-368/79-062
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, we have attached the subject reports concerning the failure of an isolation valve (2CV-2201-2) to close from a Control Room demand signal (50-368/79-060), a second isolation valve (2CV-6213-2) to close on a Control Room demand signal (50-368/79-061) and the failure of CEA #39 to move during power escalation testing (50-368/79-062).

Very truly yours

David C. Trimble

David C. Trimble
Manager, Licensing

DCT/REI/ew
Attachments

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management and Program
Analysis
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

Mr. W. D. Johnson
U. S. Nuclear Regulatory Comm.
P. O. Box 2090
Russellville, AR 72801

900010

7909040513