



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 31, 1979

D. L. ASWELL  
Vice President-Power Production

LPL 11905  
Q-3-A35.07.07  
3-A1.01.04

Mr. K. V. Seyfrit, Director, Region IV  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3  
Docket No. 50-382  
Status Report of Significant  
Construction Deficiency No. 7  
"Loose Control Element Drive  
Mechanism Guide Cones"

REFERENCE: LP&L Letter LPL 9582 dated September 12, 1978

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(e), the referenced letter submitted an Interim Report of Significant Construction Deficiency No. 7, "Loose Control Element Drive Mechanism Guide Cones." The referenced letter also indicated a planned completion date of September 1, 1979, for corrective action.

Since the issuance of the referenced letter, the work schedule within the Reactor Containment Building has been resequenced. Work is now scheduled to begin on the reactor vessel closure lead during the last quarter of 1979.

The Control Element Drive Mechanism guide cones will be corrected as specified in the interim report during this period. The final report will be forwarded by December 31, 1979.

Yours very truly,

D. L. Aswell

DLA:TFG:smd

7909120506

922 003

Boia  
S/O  
1/0

5

Mr. K. V. Seyfrid

2

August 31, 1979

cc: 1) Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

POOR  
ORIGINAL

922 004