

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A R A N O 2 00-000000-00 3 41111 4 1 5 1 6 1 7 1 8 1 9 1

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CON'T

01 L 02 05000368 03 08181879 04 091279 05 0

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Immediately following a plant trip, the Emergency Feedwater pump turbine

03 driver, 2K3, for pump 2P7A tripped on overspeed upon receipt of EFAS

04 signal. The electric driven pump, 2P7B, was started manually at approxi-

05 mately the same time as the actuation system, rather than delayed as pro-

06 grammed with auto actuation. This occurrence is similar to LER 50-368/

07 79-055. Reportable per T.S. 6.9.1.9b.

08

09 W B 11 X 12 Z 13 T U R B I N 14 Z 15 Z 16 Z

SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 COMP SUBCODE 17 18 VALVE SUBCODE 19 20

17 79 18 072 19 03 20 L 21 0

LER-NO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32

18 G 19 Z 20 Z 21 Z 22 0000 23 N 24 N 25 A 26 1147

ACTION TAKEN 33 34 FUTURE ACTION 35 36 EFFECT ON PLANT 37 38 SHUTDOWN METHOD 39 40 HOURS 41 42 ATTACHMENT SUBMITTED 43 44 NPD-4 FORM SUB 45 46 PRIME COMP SUPPLIER 47 48 COMPONENT MANUFACTURER 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The apparent cause was sticky linkage on the turbine governor; and the

11 simultaneous start of 2P7B dropping the suction pressure, thus reducing

12 the pumping resistance. Trip was reset and 2P7A successfully tested.

13 2P7A operation has been established tentatively on a weekly schedule to

14 lubricate and exercise linkage. Procedure changed to caution against

15 simultaneous pump starts.

15 B 16 0000 17 Plant Trip 18 A 19 NA 20 NA

FACILITY STATUS 21 22 % POWER 23 24 OTHER STATUS 25 26 METHOD OF DISCOVERY 27 28 DISCOVERY DESCRIPTION 29 30

16 Z 17 Z 18 NA 19 NA 20 NA

ACTIVITY CONTENT 31 32 RELEASED OF RELEASE 33 34 AMOUNT OF ACTIVITY 35 36 LOCATION OF RELEASE 37 38

16 Z 17 Z 18 NA 19 NA 20 NA

PERSONNEL EXPOSURES 39 40 NUMBER 41 42 TYPE 43 44 DESCRIPTION 45 46

17 000 18 Z 19 NA 20 NA

PERSONNEL INJURIES 47 48 NUMBER 49 50 DESCRIPTION 51 52

18 000 19 NA 20 NA

LOSS OF OR DAMAGE TO FACILITY 53 54 TYPE 55 56 DESCRIPTION 57 58

19 Z 20 NA 21 NA

PUBLICITY 59 60 ISSUED 61 62 DESCRIPTION 63 64

20 N 21 NA 22 NA

NAME OF PREPARER Chris N. Shively PHONE 501/968-2519

7909180 493

964357