

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A R A N O 2 (2) 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 (4) (5)

7 8 9 14 15 25 26 30 37 CAT 56

CON'T

01 L 6 (6) 0 5 0 0 0 3 6 8 7 (7) 0 8 2 0 7 9 8 (8) 0 9 1 2 7 9 9 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During Mode 1 operation, all CEA calculator inputs to the CPC's were

03 placed in the INOP for diagnostic testing of CEAC outputs following

04 spurious penalty factor outputs which caused a reactor trip. Continua-

05 tion of Mode 1 operation was allowed by meeting the requirements of T.S.

06 Action Statement T.S. Table 3.3-1, Action 5b. There have been no similar

07 occurrences. This occurrence is reportable per T.S. 6.9.1.9b.

08

7 8 9

09 R 10 (11) E 12 (12) E 13 (13) I N S T R U 14 (14) Y 15 (15) Z 16 (16)

7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 7 19 (17) 0 7 3 24 (24) 0 3 28 (28) L 30 (30) 0 32 (32)

21 22 23 24 25 26 27 28 29 30 31 32

18 B 19 Z 20 Z 21 Z 22 0 0 0 0 23 N 24 N 25 N 26 S 5 2 5 27 (27)

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Reporting of maintenance activity caused by necessity of entering a T.S.

11 Action Statement. The high CEAC penalty factors were caused by dirty

12 input card contacts. The edge connector was cleaned and CEAC's verified

13 operable per procedures 2304.108 and 2304.109.

14

7 8 9

15 B 28 (28) 0 0 6 29 (29) Pwr. Esc. Test 44 (44) A 45 (45) NA 46 (46)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ACTIVITY CONTENT 44 METHOD OF DISCOVERY 45 DISCOVERY DESCRIPTION 32

16 Z 33 (33) Z 34 (34) NA 44 (44) NA 45 (45) NA 46 (46)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

PERSONNEL EXPOSURES 44 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

17 0 0 0 37 (37) Z 38 (38) NA 39 (39)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

PERSONNEL INJURIES 41

18 0 0 0 40 (40) NA 41 (41)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

LOSS OF OR DAMAGE TO FACILITY 43

19 Z 42 (42) NA 43 (43)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

PUBLICITY 45

20 N 44 (44) NA 45 (45)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ISSUED DESCRIPTION 45

20 N 44 (44) NA 45 (45)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

NRC USE ONLY

NAME OF PREPARER Chris N. Shively PHONE 501/968-2519

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

7909180 498 964358