

50-327
RONS

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

August 27, 1979

79 AUG 31 19:03

USING

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


SEQUOYAH NUCLEAR PLANT UNIT 1 - DELAY OF REACTOR TRIP BECAUSE OF
ARCING ACROSS UNDERFREQUENCY RELAY CONTACTS - NCR EEB 79-13 -
FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
F. S. Cantrell on August 2, 1979, in accordance with 10 CFR 50.55(e).
Enclosed is our first interim report. We expect to submit our next
report by September 21, 1979.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
5/11

7910010293

790469

ORIGINAL COPY