



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

PRODUCTION DEPARTMENT

August 11, 1978

*Central File*  
*50-416*  
*417*

U. S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Director

Dear Sir:

SUBJECT: Grand Gulf Nuclear Station  
File 0260/15521  
IE Bulletin 78/06  
AECM-78/59

We have completed our review of IE Bulletin 78/06 concerning defective Cutler-Hammer, type M Relays with DC Coils. These relays are not used in any safety-related systems at the Grand Gulf Nuclear Station. Based on this finding, we are planning no further action in response to this bulletin.

Yours truly,

*LFD*

*for* J. P. McGaughy, Jr.  
Director of Power Production

JRF/LFD:db

cc: Mr. R. C. Travis  
Mr. T. B. Conner  
Mr. N. L. Stampley

Mr. Ernst Volgenau, Director  
Division of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

7910010620  
1032 233

Member Middle South Utilities System

*P*  
*oo' w*