

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A B V S 1 2 0 0 - 1 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 4 7 0 9 1 8 7 9 8 1 0 1 8 7 9 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 0215 hours, the No. 4 Vital Bus Inverter output frequency was observed spiking
0 3 upscale. The No. 4 Vital Bus was transferred to its alternate source and the inverter
0 4 was removed from service. The No. 2 Emergency Diesel Generator was declared
0 5 inoperable since it cannot auto-load with the No. 4 Vital Bus on its alternate power
0 6 source.

0 7
0 8
8 9

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
E D 11 E 12 A 13 G E N E R A 14 F 15 Z 16
9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
7 9 0 3 8 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A 18 B 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 A 25 X 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The frequency spiking was caused by a faulty oscillator card in the inverter control
1 1 logic. The inverter was repaired and returned to service at 0139 hours on 9/20/79.
1 2
1 3
1 4

8 9 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
1 5 E 28 0 9 9 29 N/A A 31 Operator observation
8 9 10 11 12 13 44 45 46 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 6 Z 33 Z 34 N/A N/A
7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 N/A
8 9 10 11 12 13 80

PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 8 0 0 0 40 N/A
8 9 10 11 12 80

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
1 9 Z 42 N/A
8 9 10 11 12 80

PUBLICITY ISSUED DESCRIPTION (45)
2 0 N 14 N/A
8 9 10 11 12 80

NAME OF PREPARER J. A. Werling

PHONE 412-643-1258

NRC USE ONLY

68 69 80