

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

October 16, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:


PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42
50-306 60

Tube Rupture in No. 11 Steam Generator

Enclosed are three copies of the Licensee Event Report and supplemental information for this occurrence.

This event is reported in compliance with Technical Specification 6.7.B.1(c).

Yours very truly,



L O Mayer, PE
Manager of Nuclear Support Services

LOM/JAG/ak

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
Director, Div. of Operating Reactors, NRC
(Attn: M Grotenhuis) (5)
G Charnoff
MPCA
Attn: J W Ferman

1203 132
7910230 513

5