



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366 2345

September 28, 1979

D. L. ASWELL
Vice President-Power Production

LPL 12102
Q-3-A35.07.11

Mr. K.V. Seyfrit, Director, Region IV
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Docket No. 50-382
Status of Significant Construction
Deficiency No. 11
Switchgear Breaker Position Switch
Operator Defect

Dear Mr. Seyfrit:

As discussed with your Mr. Stewart, the planned modification of the switchgear breaker position switch operators will be delayed due to the slippage of the planned shipping date of the replacement parts. We now expect to be able to submit the final report by December 1, 1979.

Yours very truly,

D.L. Aswell

DLA/TFG/ys

cc: Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

1202 289

7910240100