

**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

REPORT SOURCE 7 8 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 1 L 6 0 5 0 - 0 3 2 5 0 0 9 2 6 7 9 8 1 0 2 5 7 9 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal plant operation, the operator noticed that the containment atmospheric

03 | monitor CAC-AT-1263 was erratic. The same indication occurred on October 2, 1979

04

 Technical Specification 3.6.6.4, 6.9.1.9b

05 \_\_\_\_\_

07 \_\_\_\_\_

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

S E 11 E 12 G 13 I N S T R U 14 Y 15 Z 16

9 10 11 12 13 14 15 16

LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
17		7 9		0 5 7		0 3		L		0	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	
E 18		C 19		Z 20		Z 21		0 0 0 0		N 23	
33		34		35		36		37		41	
NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
Y 24		A 25		B 1 3 5							
42		43		44							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 In both instances, the zero reference had shifted upscale. The instrument was cali-

11 | brated both times and returned to service. Engineering is now investigating other

1 2 systems to determine the best replacement for our system, which has a history of

1 3 | calibration problems.

1	4	
---	---	--

8 9 FACILITY STATUS (1) (5) (E) (28) % POWER (0) (9) (4) (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (A) (31) DISCOVERY DESCRIPTION (32) Operator Surveillance

RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 33 4 NA NA

7 8 9 10 11 44 45

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(3)	Z	(38)	NA	(39)

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	000	(40) NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53																																																							

8 9 10 PUBLICITY 80

ISSUED DESCRIPTION (45) 7911050359 NRC USE ONLY

2 0 [N] (44) NA

7 8 9 10 68 69 80

NAME OF PREPARER A. C. Tollison, Jr.

PHONE 919-457-9521

7911050359 NRC USE ONLY

NRC USE ONLY

919-457-9521