

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N E C P R 1 2 0 0 - 0 0 0 0 - 0 0 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 2 9 8 7 0 9 1 2 7 9 8 1 0 0 9 7 9 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During steady state operation at 0915 hours, 9-12-79, an indication of possible
03 seal failure on "B" reactor recirculation (RR) pump was received. At 1309 hours, a
04 high drywell pressure alarm actuated. Power was reduced and "B" RR pump was isola-
05 ted at 1331 hours. Investigation indicates an unidentified drywell leak rate in ex-
06 cess of 5 gpm (R.T.S. 3.6.C.1) may have occurred in this 22 minute interval. The
07 plant was shutdown to replace the "B" RR pump seal. This occurrence had no ad-
08 verse affect on the public health and safety.

09 SYSTEM CODE C B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE P U M P X X 14 COMP SUBCODE B 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17
17 LER/RO REPORT NUMBER 7 9 21 22 SEQUENTIAL REPORT NO. 0 2 6 24 26 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32
ACTION TAKEN A 18 Z 19 FUTURE ACTION A 20 EFFECT ON PLANT B 21 SHUTDOWN METHOD 0 0 6 3 22 HOURS 23 ATTACHMENT SUBMITTED N 23 40 41 NPRD-4 FORM SUB. 24 PRIME COMP SUPPLIER N 25 43 COMPONENT MANUFACTURER B 5 8 0 26 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The high unidentified drywell leak rate was caused by the failure of the "B" RR
11 pump seal at its natural end of life. The seal was replaced with an identical Byron
12 Jackson shaft seal. The "A" RR pump seal was replaced in the Spring 1979 refueling
13 outage and is operating satisfactorily. No further action is planned. The RR pump
14 is a Byron Jackson Type DVSS vertical one stage pump.

15 FACILITY STATUS E 26 POWER 0 9 8 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 0 0 0 37 Z 38 NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 0 0 0 40 NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 Z 42 NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 N 44 NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER Richard Flannigan

PHONE 402-825-3811

1271 180

7911060 419

NRC USE ONLY