

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

November 21, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT - REPORTABLE DEFICIENCY - NCR HT-C-79-04 -
REBAR BENDING NOT IN ACCORDANCE WITH SPECIFICATIONS

Initial report of the subject deficiency was made to R. W. Wright, NRC-OIE, Region II, on October 23, 1979. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the first interim report of the subject deficiency. It is anticipated that the final report will be transmitted to you on or before February 8, 1979. If you have any questions concerning this matter, please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills by RLS

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1406 071

B019
5/11

7911280 412